

Lathe Power sheet – Boxford BUD 10" swing 1977

Motor compartment

Cabinet
EARTH

1 2 3

Connector 1 –
motor compartment

750w / 6A 1ph
220v AC motor

Cabinet
EARTH

1 2 3 4 5 6 7 8 9 10

Terminal 1 –
10 way

Line IN –
220v AC

to Lathe Light

to Boxford
Safety
Interlock
Switches

LED –
Power On

Terminal 1 –
2 way

Lathe light
switch

2 4

HY57B
Emergency
Stop switch

1 3

4 & 3 = not
used

24 23 13 14

KJD17B
NVR switch

**DOL Starter
compartment**

MEMLO Transformer compartment

